RESOLUTION DIRECTING WORK TO CLIFFSIDE PAVING UNDER THE BIENNIAL MISCELLANEOUS REPAIR CONTRACT

MOTIONED BY: Soares **SECONDED BY:** Velazquez

WHEREAS, the North Hudson Sewerage Authority (hereinafter "Authority) is a public body, duly formed under the Sewerage Authorities law, constituting Chapter 138 of the Laws of New Jersey of 1946, as amended (Chapter 14A of Title 40 of the New Jersey Statutes Annotated) and possesses the powers set forth therein; and

WHEREAS, the Authority has awarded a biennial contract for the Miscellaneous Repair to combined sewers of various configurations, lengths, sizes materials and their appurtenances; and

WHEREAS, the Authority awarded such a Miscellaneous Repair Contract as required by the New Jersey Contract laws to Cliffside Paving; and

WHEREAS, it is the recommendation of the Authority Engineer that Cliffside Paving, be directed to commence the work as detailed in the attached report prepared by OMI (July Project), identified as "Exhibit A", for an amount of money estimated at approximately \$58,000.

NOW, THEREFORE, BE IT RESOLVED that Cliffside Paving be directed to proceed with the work as herein noted.

DATED: AUGUST 20, 2020

	RECORD OF COMMISSIONERS' VOTE			
	YES	NO	ABSEN	Т
Commissioner Soares	Х			
Commissioner Kappock	Х			
Commissioner Marotta	Х			
Commissioner Gardiner	Х			
Commissioner Friedrich	Х			
Commissioner Sanchez	Х			
Commissioner Velazquez	Х			
Commissioner Roque			Х	
Commissioner White	Х			
THIS IS TO CERTIFY	THAT THIS	RESOLUTION	WAS DULY A	DOPTED BY TH

THIS IS TO CERTIFY THAT THIS RESOLUTION WAS DULY ADOPTED BY THE NORTH HUDSON BOARD OF COMMISSIONERS ON AUGUST 20, 2020.

SECRETARY



 Operations Management Services

 1800 Adams Street

 Hobokan: NJ 07060

 0 +1 201 795 141.

 F +1 201 420 65.0

 www.la tobs.com

August 18, 2020

Fredric J. Pocci Authority Engineer North Hudson Sewerage Authority 1600 Adams Street Hoboken, New Jersey 07030

Subject: Miscellaneous Repair Biennial Contracts: 2020-2022 August 2020 Project

Dear Mr. Pocci:

The Miscellaneous Repair Biennial Contracts: 2020-2022 will be awarded to Cliffside Paving LLC. On March 19, 2020. OMI has prepared a repair project for August 2020. The estimated costs of these repairs are based on unit prices bid by Cliffside Paving LLC.

Attached is the scope of work and estimated construction costs for the Miscellaneous Repair Biennial Contracts: 2020-2022 – August 2020 Project. OMI developed the list based on field inspections and resident concerns, and has estimated quantities and costs for the project.

The proposed August 2020 Project consists of four repairs in Hoboken, five repairs in Union City, one repair in Weehawken, and eleven repairs in West New York. The Construction costs for the twenty one repairs is estimated to be \$126,375.00 and repairs should be completed in four weeks.

If you have any questions or require additional information, please contact me.

Sincerely,

olix

Philip G. Reeve Assistant Project Director

Enclosures

Cc: Don Conger, Jacobs OMS Kevin Wynn, HMM

COMBINED SEWER - MISCELLANEOUS REPAIRS BIENNIAL CONTRACT 2020 - 2022 PROJECT SUMMARY August 2020 PROJECT NORTH HUDSON SEWERAGE AUTHORITY 8/10/2020

OWNER: NORTH HUDSON SEWERAGE AUTHORITY 1600 ADAMS STREET HOBOKEN, NJ 07030

CONTRACTOR Cliffside Paving LLC. 75 Lincoln Avenue Cliffside Park NJ

PROJECT	DESCRIPTION	ESTIMATED
		COST
1	Hoboken Project #1 - 2nd Street & Adams Street NE corner Collapsed catch basin	\$5,000.00
2	Hoboken Project #2 - 2nd Street & Adams Street SW corner Collapsed catch basin	\$5,000.00
3	Hoboken Project #3- 2nd Street & Adams Street NW corner Collapsed catch basin	\$5,000.00
4	Hoboken Project #4- 5th Street & Hudson Street NE corner Collapsed catch basin	\$5,000.00
5	Union City Project #1- #3700 Bergenline Ave- Severely worn manhole casting	\$2,875.00
6	Union City Project #2- 10th Street & West Street NW corner Collapsed catch basin	\$5,000.00
7	Union City Project #3- 10th Street & West Street SW corner Collapsed catch basin	\$5,000.00
8	Union City Project #4- 10th Street & West Street NE corner Collapsed catch basin	\$5,000.00
9	Union City Project #5- 2nd Street & Bergenline - Collapsed manhole 🖌	\$8,500.00
10	Weehawken Project #1- 20th Street & Mountain Road SW corner Collapsed catch basin	\$5,000.00
11	West New York Project #1- 56th Street & Bergenline Ave SW corner Collapsed catch basin	\$5,000.00
12	West New York Project #2-56th Street & Bergenline Ave SE corner Collapsed catch basin	\$5,000.00
13	West New York Project #3- 56th Street & Bergenline Ave NW corner Collapsed catch basin	\$5,000.00
14	West New York Project #4- 62nd Street & Bergenline Ave NE corner Collapsed catch basin	\$5,000.00
15	West New York Project #5- 54th Street & Bergenline Ave NW corner Collapsed catch basin	\$5,000.00
16	West New York Project #6- 59th Street & Jefferson Ave NE corner Collapsed catch basin	\$5,000.00
17	West New York Project #7- 61st Street & Washington Ave SW corner Collapsed catch basin	\$5,000.00
18	West New York Project #8- 61st Street & Washington Ave SE corner Collapsed catch basin	\$5,000.00
19	West New York Project #9- #412 62nd Street Collapsed Manhole	\$5,000.00
20	West New York Project #10- 59th Street & Jackson St Broken pipe	\$15,000.00
21	West New York Project #11- 58th Street btwn Broadway & Park Ave Broken pipe 🖍	\$15,000.00

\$126,375.00

DATE: 8/10/2020

WORK ORDER NO. 1

PRIORITY 1

2nd & Adams NE corner Hoboken

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

APPROVED----

DATE: 8/10/2020

WORK ORDER NO. 2

PRIORITY 1

2nd & Adams st. SW corner Hoboken

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

()APPROVED-----C

DATE: 8/10/2020

WORK ORDER NO. 3 PRIORITY

1

2nd & Adams St NW corner Hoboken

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

APPROVED--

DATE: 8/10/2020

WORK ORDER NO. 4

PRIORITY 1

5th Street & Hudson Street NE corner Hoboken

PIPE SIZE: DEPTH OF PIPE:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

APPROVED--

DATE: 8/10/2020

WORK ORDER NO. 1 PRIORITY

1

#3700 Bergenline Ave. Union City

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Severely worn manhole casting

RECOMMENDATION

Replace manhole casting

APPROVED-----

dui

DATE: 8/10/2020

WORK ORDER NO. 2 PRIORITY 1

10th Street & West Street NW corner Union City

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair Collapsed catch basin

APPROVED-----

DATE: 8/10/2020

WORK ORDER NO. 3 PRIORITY 1

10th Street & West Street SW corner Union City

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair Collapsed catch basin

APPROVED--

DATE: 8/10/2020

WORK ORDER NO. 4

PRIORITY 1

10th Street & West Street NE corner Union City

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair Collapsed catch basin

APPROVED-

DATE: 8/10/2020

WORK ORDER NO. 5

PRIORITY 1

2nd Street & Bergenline Ave Union City

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed Manhole

RECOMMENDATION

Repair Collapsed manhole

APPROVED----

1

DATE: 8/10/2020

WORK ORDER NO. 1

PRIORITY

20th Street & Mountain Road SW corner Weehawken

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair Collapsed catch basin

APPROVED----

DATE: 8/10/2020

WORK ORDER NO. 1 PRIORITY 1

56th and Bergenline SW corner West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

APPROVED---

DATE: 8/10/2020

WORK ORDER NO. 2 PRIORITY 1

56th and Bergenline SE corner West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

APPROVED-----

DATE: 8/10/2020

WORK ORDER NO. 3

PRIORITY 1

56th and Bergenline NW corner West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

APPROVED-----

DATE: 8/10/2020

WORK ORDER NO. 4 PRIORITY 1

62nd & Bergenline Ave NE corner West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

APPROVED----

1

DATE: 8/10/2020

WORK ORDER NO. 5

PRIORITY

54th & Bergenline Ave NW corner West New York

PIPE SIZE: DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

APPROVED----

DATE: 8/10/2020

WORK ORDER NO. 6

PRIORITY 1

59th & Jefferson St NE corner West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

in APPROVED--

DATE: 8/10/2020

WORK ORDER NO. 7

PRIORITY 1

61st & Washington St SW corner West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin.

APPROVED----

DATE: 8/10/2020

WORK ORDER NO. 8 PRIORITY 1

61st & Washington St SE corner West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin

APPROVED--

DATE: 8/10/2020

WORK ORDER NO. 9

PRIORITY 1

#412 62nd St Manhole repair West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Collapsed manhole

RECOMMENDATION

Repair collapsed manhole

APPROVED----

DATE: 8/10/2020

WORK ORDER NO. 10

PRIORITY 1

59th & Jackson Street West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



DESCRIPTION

Broken pipe

RECOMMENDATION

Repair Broken pipe

APPROVED----

DATE: 8/10/2020

WORK ORDER NO. 11 PRIORITY

1

58th btwn Broadway & Park West New York

PIPE SIZE:

DEPTH OF PIPE:

PIPE MATERIAL:



APPROVED-----

DESCRIPTION

Collapsed catch basin

RECOMMENDATION

Repair collapsed catch basin